



# HMS Security Advisory Report

## HMSSAR-2024-01-12-001

Publication date: 12 January 2024

Last update: 6 June 2024

### Overview

- 1) Vulnerability in MQX RTOS affecting DHCP client (CVE-2017-12718). This third party closed source library provides the implementation of DHCP Client in most Intesis products with Ethernet port.
- 2) Overflow vulnerability in UDP stack
- 3) High traffic vulnerability in UDP stack

### Impact

- 1) DHCP Client: In order to exploit this vulnerability, a man-in-the-middle attack must be executed by faking the DHCP Server and sending a malicious frame. Successful exploitation of this vulnerability may allow a remote attacker to cause a denial of service or execute code on the target device.
- 2) UDP overflow: Allows remote code execution using a malicious UDP frame. Protocols affected are BACnet and console.
- 3) UDP high traffic: Can provoke a reset of the gateway (DoS) by sending a high rate of UDP packets.

### Affected products and versions

- Intesis BACnet AC Interfaces:

| Ordercode       | FW name      | Version <= |
|-----------------|--------------|------------|
| INBACMIT001I000 | ME-AC-BAC-1  | 2.0.5.0    |
| INBACDAI001I000 | DK-AC-BAC-1  | 2.0.4.0    |
| INBACPAN001R000 | PA-RC2-BAC-1 | 2.0.3.0    |
| INBACHIT001R000 | HI-RC-BAC-1  | 1.0.0.0    |
| INBACPAN001I000 | PA-AC-BAC-1  | 2.0.3.0    |
| INBACDAI001R000 | DK-RC-BAC-1  | 1.0.7.0    |
| INBACMHI001R000 | MH-RC-BAC-1  | 1.0.3.0    |

- Intesis Protocol Translators:

| Ordercode       | FW name         | Version <= |
|-----------------|-----------------|------------|
| INKNXFGLccc00oo | FJ-AC-KNX       | 1.0.1.0    |
| INMBSFGLccc00oo | FJ-AC-MBS       | 1.0.2.0    |
| INBACHITccc00oo | HI-AC-BAC       | 1.0.4.0    |
| INKNXHITccc00oo | HI-AC-KNX       | 1.0.4.0    |
| INMBSHITccc00oo | HI-AC-MBS       | 1.0.3.0    |
| INBACHISccc00oo | HS-AC-BAC       | 1.0.2.0    |
| INKNXHISccc00oo | HS-AC-KNX       | 1.0.1.0    |
| INMBSHISccc00oo | HS-AC-MBS       | 1.0.3.0    |
| INASCBACccc00oo | IBOX-ASCII-BAC  | 1.0.2.0    |
| INASCKNXccc00oo | IBOX-ASCII-KNX  | 1.0.1.0    |
| INBACDALccc00oo | IBOX-BAC-DALI   | 1.1.3.0    |
| INBACEIP1K20000 | IBOX-BAC-EIP    | 1.0.2.0    |
| INBACKNXccc00oo | IBOX-BAC-KNX    | 1.0.6.0    |
| INBACLONccc0000 | IBOX-BAC-LON    | 1.0.3.0    |
| INBACMBMccc00oo | IBOX-BAC-MBM    | 1.1.4.0    |
| INBACMBM1000200 | IBOX-BAC-MBM-2S | 1.0.1.0    |
| INBACMEBccc00oo | IBOX-BAC-MBUS   | 1.0.10.0   |
| INBACPRT1K20000 | IBOX-BAC-PRT    | 1.0.2.0    |
| INBACRTR03200oo | IBOX-BAC-RTR    | 1.0.1.0    |
| INBACDAL0640500 | IBOX-BACIP-DALI | 1.1.1.0    |
| INBACMBMccc01oo | IBOX-BACIP-MBM  | 1.0.2.0    |
| INBACMEBccc0100 | IBOX-BACIP-MBUS | 1.0.1.0    |
| INSTCMBGccc00oo | IBOX-I4B-TCP    | 1.0.8.0    |
| INKNXBACccc0000 | IBOX-KNX-BAC    | 1.0.3.0    |

|                 |                 |          |
|-----------------|-----------------|----------|
| INKNXDAL0640000 | IBOX-KNX-DALI   | 1.1.1.0  |
| INKNXMBMccc0000 | IBOX-KNX-MBM    | 1.0.8.0  |
| INKNXMEBccc0000 | IBOX-KNX-MBUS   | 1.0.3.0  |
| INKNXBACccc0000 | IBOX-MBS-BAC    | 1.0.3.0  |
| INMBSDALccc00oo | IBOX-MBS-DALI   | 1.1.2.0  |
| INMBSKNXccc0000 | IBOX-MBS-KNX    | 1.0.5.0  |
| INMBSMEBccc0000 | IBOX-MBS-MBUS   | 1.0.7.0  |
| INMBSOCPccc0100 | IBOX-MBS-OCPP   | 1.0.3.0  |
| INMBSRTR03200oo | IBOX-MBS-ROUTER | 1.0.2.0  |
| INMBSDAL0640500 | IBOX-MBTCP-DALI | 1.1.1.0  |
| INMBSMEBccc0100 | IBOX-MBTCP-MBUS | 1.0.3.0  |
| INKNXLGEccc00oo | LG-AC-KNX       | 1.0.3.0  |
| INMBSLGEccc00oo | LG-AC-MBS       | 1.0.0.0  |
| INKNXMITcccC0oo | ME-AC-KNX       | 1.0.3.0  |
| INMBSMITcccC0oo | ME-AC-MBS       | 1.0.8.0  |
| INBACMID004I000 | MD-AC-BAC       | 1.0.2.0  |
| INBACPANcccO0oo | PA-AC-BAC       | 1.0.6.0  |
| INKNXPANcccO0oo | PA-AC-KNX       | 1.0.2.0  |
| INMBSPANcccO0oo | PA-AC-MBS       | 1.0.5.0  |
| INBACSAMcccO0oo | SM-ACN-BAC      | 1.0.10.0 |
| INKNXSAMcccO0oo | SM-ACN-KNX      | 1.0.7.0  |
| INMBSSAMcccO0oo | SM-ACN-MBS      | 1.0.8.0  |

## Severity / CVSS Score

The following CVE has been fixed in the products:

### 1) DHCP Client

| CVE ID         | CVSS 3.1 Rating | CVSS 3.1 Vector                              |
|----------------|-----------------|----------------------------------------------|
| CVE-2017-12718 | 7,5             | CVSS:3.1/AV:N/AC:H/PR:N/UI:R/S:U/C:H/I:H/A:H |



- 2) UDP Overflow  
CVSS v3.1: [9.1](#)  
[\(AV:N/AC:L/PR:N/UI:N/S:C/C:L/I:L/A:L/E:U/RL:X/RC:C/CR:X/IR:X/AR:X/MAV:N/MAC:L/MPR:N/MUI:N/MS:C/MC:H/MI:H/MA:H\)](#)
- 3) UDP High Traffic  
CSVV v3.1: [7.9](#)  
[\(AV:N/AC:L/PR:N/UI:N/S:C/C:L/I:L/A:L/E:U/RL:X/RC:C/CR:X/IR:X/AR:X/MAV:N/MAC:L/MPR:N/MUI:N/MS:C/MC:N/MI:N/MA:H\)](#)

## HMS Recommendations

HMS recommends updating all the products installed in the field. An alternative solution is disabling DHCP and setting fixed IP settings.

## Product updates

The vulnerability is already fixed. All versions higher than the ones listed above are not affected by it.

## Additional information

The MQX security issue was first reported here: <https://cve.mitre.org/cgi-bin/cvename.cgi?name=CVE-2017-12718>